

COMPREHENSIVE SERVICES

We offer competitive repair and calibration services, as well as easily accessible documentation and free downloadable resources.

SELL YOUR SURPLUS

We buy new, used, decommissioned, and surplus parts from every NI series. We work out the best solution to suit your individual needs.


 Sell For Cash  Get Credit  Receive a Trade-In Deal

OBSOLETE NI HARDWARE IN STOCK & READY TO SHIP

We stock **New**, **New Surplus**, **Refurbished**, and **Reconditioned** NI Hardware.



Bridging the gap between the manufacturer and your legacy test system.

 1-800-915-6216

 www.apexwaves.com

 sales@apexwaves.com

All trademarks, brands, and brand names are the property of their respective owners.

Request a Quote

 **CLICK HERE**

PXIe-1071

Product Notification: Possible System Hang with Third-Party PXI Modules for some National Instruments PXI Systems with a 64-bit Operating System.

There is a limitation with some National Instruments PXI and PXI Express chassis which may cause a system hang or crash if a PXI, PXI-1, or hybrid-compatible PXI module attempts 64-bit memory addressing transactions. This limitation occurs when a PXI-1 or hybrid-compatible module attempts memory transactions in affected PXI systems running a 64-bit Operating System (OS) with more than 4 GB of system RAM. This limitation impacts PXI-1 and hybrid-compatible PXI modules using 64-bit memory transactions only; there is no impact on PXI Express modules.

The following chassis may exhibit this behavior if 64-bit memory addressing is used to communicate with a PXI-1 or hybrid compatible PXI module:

- NI PXI-1033
- NI PXIe-1062Q
- NI PXIe-1065
- NI PXIe-1071
- NI PXIe-1073
- NI PXIe-1075
- NI PXIe-1082

NI has updated certain hardware drivers for its PXI modules to resolve this limitation. Please visit ni.com/info and enter the Info Code `PXI64HANG` for additional information regarding driver changes that address this constraint.

Action Required

If you are using a 32-bit OS in standard, non-PAE mode then you are not affected by this limitation and no further action is required.

If you plan to upgrade the OS on an existing PXI system to a 64-bit OS; then we request you to upgrade to the latest NI hardware drivers in order to avoid this limitation.

If you are using a third-party PXI-1 or hybrid compatible PXI device in your chassis that uses 64-bit memory addressing please refer to the Knowledgebase article linked by the Info Code above.